

UK Statement of Compliance


For the purposes of UK SI 2023 No. 1007 (PSTI Regulations) **Pittway Sarl of Z.A. La Pièce 6, 1180 Rolle, Switzerland** (Manufacturer) declares that this Statement of Compliance has been prepared by or on its behalf and that, in its opinion, it has complied with the applicable security requirements in Schedule 1 of the PSTI Regulations in respect of the following products, each listed with its defined support period (where applicable) from the time of the Manufacturer's first supply:

1. **Product:** 50034501-013, **Type:** Boiler Relay box, **Firmware version:** V29, **Min. support period:** incapable of receiving firmware updates.
2. **Product:** 50034501-015, **Type:** Boiler Relay box, **Firmware version:** V29, **Min. support period:** incapable of receiving firmware updates.
3. **Product:** ATC928G3000, **Type:** evohome - Connected Thermostat, **Firmware version:** V2.1.0 and later, **Min. support period:** 24 months after Resideo's last order date.
4. **Product:** BDR91A1000, **Type:** Boiler Relay box, **Firmware version:** V29, **Min. support period:** incapable of receiving firmware updates.
5. **Product:** BDR91T1004, **Type:** Boiler Relay box, **Firmware version:** V1.10, **Min. support period:** incapable of receiving firmware updates.
6. **Product:** THR822B, **Type:** Boiler Relay box, **Firmware version:** V29, **Min. support period:** incapable of receiving firmware updates.
7. **Product:** R4H810A1004, **Type:** Boiler Relay box, **Firmware version:** V04.00.04.10 and later, **Min. support period:** 24 months after Resideo's last order date.
8. **Product:** R4H910RF1004, **Type:** Boiler Relay box, **Firmware version:** V04.00.04.10 and later, **Min. support period:** 24 months after Resideo's last order date.
9. **Product:** R6H911RF4018, **Type:** Boiler Relay box, **Firmware version:** V04.00.04.10 and later, **Min. support period:** 24 months after Resideo's last order date.
10. **Product:** R8810A, **Type:** Boiler Relay box, **Firmware version:** V11, **Min. support period:** incapable of receiving firmware updates.
11. **Product:** T6H600WF1003, **Type:** T6 - Connected Thermostat, **Firmware version:** V04.00.04.10 and later, **Min. support period:** 24 months after Resideo's last order date.
12. **Product:** T6H600WF1015, **Type:** T6 - Connected Thermostat, **Firmware version:** V04.00.04.10 and later, **Min. support period:** 24 months after Resideo's last order date.
13. **Product:** T6H700RW4011, **Type:** T6 - Connected Thermostat, **Firmware version:** V04.00.04.10 and later, **Min. support period:** 24 months after Resideo's last order date.
14. **Product:** T6H700RW5001, **Type:** T6 - Connected Thermostat, **Firmware version:** V04.00.04.10 and later, **Min. support period:** 24 months after Resideo's last order date.
15. **Product:** TTHWFD Relay Box, **Type:** Boiler Relay box, **Firmware version:** V29, **Min. support period:** incapable of receiving firmware updates.
16. **Product:** TTHWFP Relay Box, **Type:** Boiler Relay box, **Firmware version:** V29, **Min. support period:** incapable of receiving firmware updates.

The Manufacturer has appointed **Ademco 1 Ltd** of **Newhouse Industrial Estate, Motherwell, Scotland, ML1 5SB** as its authorised representative.

See hwll.co/DoC for the latest version of this statement.

Issued on 19th February 2024 at Motherwell, UK



Shaji Varghese, Engineering Director

R32352320-001